


BMW OEM Software ISTA-P and TABSCAN J2534 Connection Guide


Note: Please install the BMW OEM software before use. Any questions about OEM software setup please feel free to contact us.

1. Create your TABSCAN account with email or phone number, and log in.




The screenshot shows a web browser window titled "Register" for "TabScan J2534". The page has a close button (X) in the top right corner. The main heading is "Register". Below it, a welcome message says "Welcome to TabScan J2534". The form contains three input fields: "Account" (labeled "Input account"), "Verification Code" (labeled "Input verification code"), and "New Password" (labeled "Input new password"). To the right of the "Verification Code" field is a button labeled "Get verification code". At the bottom of the form is a large blue button labeled "Confirm". The "Account" field is highlighted with a red rectangular border.


2. Connect the device to your PC using the provided USB cable. Check whether there is an update notice on the top left corner. **For optimal performance, please upgrade to the latest firmware version when available on the TABSCAN platform.**




The screenshot shows the TabScan J2534 1.0.0 software interface. At the top left, there is a status bar with a green checkmark icon, the text "T6CC0000J1100002", and "Vehicle voltage 0.32 V". A red box highlights this status bar. To the right of the status bar are three buttons: "Login / Register", "Settings", and a help icon. Below the status bar, the "Current Driver" section shows "VW" with a dropdown arrow and "Not Installed". Below this, a "New Version 1.9.0" section is displayed, showing the size "2.96 MB" and the publication date "09/01 08:46". A blue "Install" button is located to the right of this section. Below the "New Version" section, a "Version description" is provided: "1. Fix the problem that Volkswagen doip does not communicate." At the bottom, a "Tutorials" section is visible, with the text: "Install the OEM software first, then download and install the corresponding OEM drivers to perform diagnostics and programming. Feel free to contact us if you need help."




3. Click the drop-down arrow of the current driver, select the **BMW driver** to install.
Note: For the stability of the program, it's better to only have one vehicle brand driver installed at a time.




4. Make sure the driver is enabled before using OEM software to diagnose.




5. Double click the OEM software **ISTA-P** icon to open.



6. Choose the BMW icon



7. Click “Create new session”, choose “Select ISTA/P server automatically”, then click “Continue”.



8. Choose the VIN that appears in the Connection manager and click “Connect” to start diagnosing.

